


9. Drawing PIRINEOS 60



10. PARTS BREAKDOWN DIAGRAMME

POS.	DESCRIPTION	POS.	DESCRIPTION
1	Trestle leg	34	Washer DIN 9021 Ø10
2	Leg cont trestle	35	Wing M-8
3	Trestle table	36	Butterfly nut M-6
4	Tray	37	Washer DIN 9021 Ø6
5	Cutting table	38	Screw DIN 603 M-6X16
6	Butt cut	39	Handel
7	Head	40	Hex nut M-10
8	Right crus	41	Washer DIN 125 Ø10
9	Left crus	42	Head bearing set
10	Bridge profile	43	Hex screw M-10x30
11	Housing	44	Hex screw M-8x16
12	Housing rubber	45	Washer DIN 9021 Ø8
13	Electricity supply box	46	Self-locking nut M-8
14	Left hand thread nut M-20	47	Screw DIN 603 M-8X15
15	External plate	48	Washer DIN 9021 Ø8
16	Diamond blade Ø200	49	Wing M-8
17	Internal plate Ø22.2	50	Sheet metal screw thread
18	Motor II 1.1 kw	51	Plaque characteristics
19	Goniometer		
20	Cutting gauge		
21	Wire rod		
22	Cooling system		
23	Submergible pump		
24	Plug tray		
25	Rubber set		
26	Screw DIN 603 M-8x35		
27	Washer DIN 9021 Ø 8		
28	Wing M-8		
29	Hex screw M-10x40		
30	Washer DIN 9021 Ø 10		
31	Washer DIN 9021 Ø 10		
32	Self-locking nut M-10		
33	Screw DIN 603 M-8x16		