


9. EXPLODED VIEW



10. SPARE PARTS LIST

Item No.	Part No.	Description	Qty.
1		Water plug	1
2		Extraction hose	2
3		Electric motor	1
4		Hexagon head screw M10x45	4
5		Washer Ø10 mm	4
6		Handle holder (above)	2
7		On-Off-Switch cpl.	1
8		Plug	2
9		Handle	1
10		Hexagon head screw M10x60	1
11		Washer Ø10 mm	1
12		Handle holder (on the side)	1
13		Hexagon head screw M8x20	4
14		Washer Ø8 mm	4
15		Nut M8	4
16		Crank handle	1
17		Hexagon head screw M8x25	4
18		Washer Ø8 mm	4
19		Elbow-fitting	2
22		Nut M8	4
24		Spindle with spindle nut	1
25		Washer Ø12 mm	1
26		Hexagon head screw M12x65	1
27		Locking ring	2
29		Wheel	2
30		Wheel axle	1
31		Nut M12 (self-locking)	1
32		Countersunk screw	6
33	85-1009	Tool fitting plate	1
34	85-1090	Brush ring (outside)	1
35		Tool cover	1
36	85-1091	Brush ring (inside)	1
37 *		V-belt pulley (tool fitting side)	1
38		Chassis	1
39		V-belt	3
40		V-belt pulley (motor side)	1
41		Washer Ø10 mm	2
42		Hexagon head screw M10x65	2
43		Flange	1
44		Washer Ø10 mm	6
45		Hexagon socket screw	6
46		Water connection	1
47		Water hose	1
48		Hexagon spanner Ø12 mm (without figure)	1
49		GEKA-Coupling (without figure)	1

* 37a 85-1010 Rugalmas tengelykapcsoló 1

37b 85-MS48000309 Tartó tányér 1