


## AGT 4-600 W



| PART NO.  | DESCRIPTION            | QTY |
|-----------|------------------------|-----|
| PT2401    | Handle (above)         | 1   |
| PT2402    | Switch                 | 1   |
| PT2403    | Throttle lever         | 1   |
| PT2404    | Throttle cable         | 1   |
| PT2405    | Handle (below)         | 1   |
| PT2406    | Connect screw, handle  | 1   |
| PT2407    | Clamping screw         | 1   |
| PT2408    | Adjusting handle       | 1   |
| PT2409    | Fixed seat             | 1   |
| PT2410    | Adjusting screw        | 1   |
| PT2411    | Screw stem             |     |
| PT2412    | Installing Gasket      | 1   |
| PT2413    | Shaft, knock pin       | 1   |
| PT2414    | Fixed plate, knock pin | 1   |
| PT2415/17 | Blade fixer            | 4   |
| PT2416    | Blade                  | 4   |
| PT2418    | Socket head bolt M8    | 1   |
| PT2419    | Adjusting screw        | 1   |
| PT2420    | Cross                  | 1   |
| PT2421    | Knock pin              | 1   |
| PT2422    | Key6*6*25              | 1   |
| PT2423    | Spindle                | 1   |

|        |                              |   |
|--------|------------------------------|---|
| PT2424 | Below plate                  | 1 |
| PT2425 | Bearing 6808z                | 1 |
| PT2426 | Plane bearing 644808 NK45/20 | 1 |
| PT2427 | Clamp springφ18              | 1 |
| PT2428 | Plane bearing ASK3552-LS     | 1 |
| PT2429 | Plate                        | 1 |
| PT2430 | Reduction box                | 1 |
| PT2431 | Engine mounting plate        | 1 |
| PT2432 | Engine                       | 1 |
| PT2433 | Key6*6*20                    | 1 |
| PT2434 | Clutch                       | 1 |
| PT2435 | Belt A25                     | 1 |
| PT2436 | Pulley                       | 1 |
| PT2437 | Key6*6*30                    | 1 |
| PT2438 | Pan (Aluminium)              | 1 |
| PT2439 | Fixed ring,                  | 1 |
| PT2441 | Belt Cover                   | 1 |
| PT2442 | Rubber ring φ800, pan        | 1 |
| PT2443 | Plane bearing51110           | 1 |
| PT2444 | Stay wire guidance           | 1 |
| PT2445 | Spindle Washer               | 1 |
| PT2446 | Screw                        | 1 |